

	Type	L #	Hits	Search Text	DBs	Time Stamp	Cor ro mm en ts	De fi ni ti on	Err ro mm en ts	Err ro mm en ts
1	BRS	L1	107	@pd>"20060530" and thermoplastic and (charge\$1control or (charge control))	US- PGPUB; USPAT	2006/10/20 15:19				
2	BRS	L2	3690	@pd>"20060530" and thermoplastic and (pigment or colo\$1r or colo\$1ring or colo\$1rant\$1)	US- PGPUB; USPAT	2006/10/20 15:20				
3	BRS	L3	0	1 and (252/62.5\$.ccls. or 252/62.6\$.ccls.)	US- PGPUB; USPAT	2006/10/20 15:22				
4	BRS	L4	85	1 and magnet\$	US- PGPUB; USPAT	2006/10/20 15:22				
5	BRS	L6	922	2 and magnet\$	US- PGPUB; USPAT	2006/10/20 15:22				
6	BRS	L5	1	2 and (252/62.5\$.ccls. or 252/62.6\$.ccls.)	US- PGPUB; USPAT	2006/10/20 15:22				

	Type	L #	Hits	Search Text	DBs	Time Stamp	Cor re cti on	De ni ti on	Err or ors
7	BRS	L7	478	(4 or 6) and (compression\$mol d\$ or mold\$)	US- PGPUB; USPAT	2006/10/20 15:23			
8	BRS	L8	6	(4 or 6) and ((compression\$mo ld\$ or mold\$) same (magnetic field))	US- PGPUB; USPAT	2006/10/20 15:23			